

Telephone:
Fax:
VAT Registration No.:

Name:		Manufacturer:	Fiat
Address:		Model:	Bravo 2.0
		Year:	1995-1998
		Registration:	
Tel - Private:		Mileage:	
Tel - Business:		Job number:	

Ignition system

Ignition coil

Component disconnected

Fig. 43146

Terminals	Condition	Typical value	Note
2 & 3	Ignition ON	11-14 V	1

Notes

1. Checking supply voltage.

Ignition coil

Component disconnected

Fig. 83282

Terminals	Condition	Typical value	Note
1 & 3		0,4 W	2,3

Notes


2. Checking primary resistance.
3. Secondary resistance cannot be checked.

Manufacturer: Fiat
Engine code: 182A1.000
Tuned for: R-Cat


Model: Bravo 2,0
Output: 108 (147) 6100
Year: 1995-98

© Autodata Limited 2004
31.08.06
V5.373- ***/Autodata***

43146



83282



Manufacturer: Fiat
Engine code: 182A1.000
Tuned for: R-Cat

Model: Bravo 2,0
Output: 108 (147) 6100
Year: 1995-98

© Autodata Limited 2004
 31.08.06
 V5.373- **/Autodata**