



Vehicle	Fiat Marea 1,9 JTD 105 / 1,9 / 77 // 1999 - 2000 / 182B4.000
Country of manufacture	-
Cubic capacity/Power	1,9 / 77 kW
Motor tag	182B4.000
RB key	FIA 1370 (FIA10097)

Known fixes and bulletins

Bulletin

- Driveability
- Engine mechanical
- Noise, vibration and harshness

Affected vehicles

- All models with 1,9D JTD engine.

Problem

- Metallic noise from auxiliary drive belt area for approximately 2 minutes after cold start.

Cause

- Auxiliary drive belt tensioner.

Remedy

- Renew auxiliary drive belt tensioner.